

HABS  
ALA  
49-MOBI,  
4-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Southern Market and Municipal Building (City Hall)  
111 South Royal Street  
Mobile  
Mobile County  
Alabama

HABS No. AL-5

Addendum to  
City Hall (French Market)  
111 South Royal Street  
Mobile  
Mobile County  
Alabama  
in HABS Catalog (1941)

AL-5-1 through AL-5-19 previously transmitted to the Library of Congress  
Jack E. Boucher, photographer, January 1963

AL-5-20	General view of west (front) elevation
AL-5-21	Central block, west elevation
AL-5-22	East Elevation
AL-5-23	South Elevation
AL-5-24	Detail of pediment with ornate brackets, west elevation
AL-5-25	Cupola detail
AL-5-26	Detail of wire grille transom

ADDENDUM  
FOLLOWS...



HABS  
ALA,  
49-MOBI  
4-

# HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Southern Market and Municipal Building (City Hall)  
107-115 South Royal St.  
Mobile  
Mobile County  
Alabama

HABS No. AL-5

Addendum to:

City Hall (Southern Market)  
111 South Royal St.  
Mobile  
Mobile County  
Alabama

Photographs AL-5-1 through AL-5-26 were previously transmitted to the Library of Congress

Carl V. Kling, AIA, photographer, August 1981

AL-5-27	S. Royal St. (main) elevation
AL-5-28	S. Royal St. elevation, at angle
AL-5-29	Middle bays of S. Royal elevation
AL-5-30	Church St. (south) elevation
AL-5-31	Waster St. (rear) elevation from southeast
AL-5-32	Water St. elevation from northeast
AL-5-33	Central bays of Water Street elevation
AL-5-34	Courtyard, central bays of rear of main elevation
AL-5-35	Courtyard, central bays of rear of rear elevation
AL-5-36	Courtyard, rear and side of central bays of rear elevation
AL-5-37	Courtyard, behind belfry
AL-5-38	Belfry
AL-5-39	Interior, corridor
AL-5-40	Interior, corridor and stairs in front of planning commission office
AL-5-41	Interior, council chamber, looking toward dias



HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS No. AL-5  
(page 2)

AL-5-42 Interior, council chamber, towards rear of room

Nicholas H. Holmes III, AIA, photographer, 1983, photocopies made from original  
color prints shot by Mr. Holmes

AL-5-43 S. Royal St. (main) and Church St. (south) elevations

AL-5-44 Courtyard, looking northeast

AL-5-45 Courtyard, looking north

AL-5-46 Courtyard, looking east, along alley

AL-5-47 Courtyard, looking south

AL-5-48 Courtyard, passageway

AL-5-49 Courtyard, looking north, showing skywalk in distance

AL-5-50 Interior, unidentified staircase

AL-5-51 Interior, unidentified corridor

AL-5-52 Interior, reception room

AL-5-53 Interior, office

AL-5-54 Interior, council chamber

AL-5-55 Interior, hearing room

N.B. Mr. Kling's photographs show the unoccupied city hall after it had been severely damaged by a 1979 hurricane. Mr. Holmes's photographs show the city hall after it was restored by his father's architectural firm. (The building was documented in the 1930s by <sup>the</sup> first Nicholas Holmes, for HABS).